



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Pitt PERMIT NO.: SLAS-74-08 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 8/16/2012 **Date of Last Inspection:** 4/4/2012

FACILITY NAME AND ADDRESS:

*Alton J. Cannon
Cannons Septic Tank Service, Inc.
PO Box 65
Grifton, NC 28530*

GPS COORDINATES:

N: 35.35508

W: -77-35309

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Scott Maready*
Telephone: *252-524-4282*
Email address: *cannonsseptic tankservice@embarqmail.com*
Fax: *(252) 524-3282*

FACILITY CONTACT ADDRESS:

Same as above.

PARTICIPANTS: *Chester Cobb*

STATUS OF PERMIT: *Active*

EXPIRES: *3/15/2017*

PURPOSE OF SITE VISIT: *Routine*

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the previous inspection conducted on 4/4/12.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Signage present as you get to Fields 7 and 8. Signage present as you get to Field 6 also.
2. Access road was in good shape.
3. All markers were present.
4. No septage discharges noticed outside of the permitted boundaries of the fields.
5. No spot dumps or thick applications noticed.
6. Field 6 will need to be cut soon. Fields 7 and 8 had been cut with grass starting to grow again. A lot of crabgrass noticed on the fields. The bermudagrass appeared either yellow or brown in all the fields. Did not notice any trumpetweed (weed) within Field 6.
7. No application at time of discharge. pH not checked.
8. No objectionable odors noticed.
9. No change noticed with any of the setbacks. There is a 50 ft setback to the bordering field crops.
10. Records not checked.
11. The bermudagrass looked like it was dying. Maybe lack of nutrients or drier conditions?

Please contact me if you have any questions or concerns regarding this inspection report.



Chester R. Cobb

Regional Representative

Phone: (919) 707-8283.

Sent on: 7/25/13		Email		Hand delivery	X	US Mail		Certified No. <u> </u>
------------------	--	-------	--	---------------	----------	---------	--	-------------------------